## TO BE FILLED BY THE INSPECTING OFFICER

(Assistant Engineer)

Name of School: Chinmaya Vidhyalaya, Ambattuparambu, Thathamangalam PALAKKAD Dist. Education District: Palakkad Sub Dist: Palakkad

## (Provisional)

(Provisional)	
: Sudha.S	
: Pattanchery Grama Panchayath	
: 2023-24	
. 2023-24	
: 1X6.22X8.00X3.60	
: 1X6.22X8.00X3.00	
: 1X6.26X8.00X3.60	
: 1X6.26X7.96X3.60	
: 1X6.26X7.96X3.60	
: 6X6.07X7.96X3.60	
: 1X6.76X8.75X3.60	
: 1X10.89X1.97X3.60	
: 1X5.63X7.96X3.60	
: 1X4.98X9.34X3.60	
: 1X3.62X3.15X3.60	
: 1X6.07X7.96X3.60	
: 1X5.50X8.75X3.60	
: 1X6.22X7.74X3.60	
: 1X2.06X1.50X3.60	
: 1X1.64X2.66X3.60	
: 1X1.30X1.47X3.60	
: 1X6.07X7.96X3.60	
: 1X94.20X1.54X3.60	
: 1X 7.50 X 12.20 X3.60	
: 1X 9.62X2.84X3.60	
: 1X 7.50X12.20X3.60	
: 1X13.87X3.45X3.60	
: 1X25.26X1.88X3,60	
: 1X4.15X1.97X3.60	
: 1X6.22X8.00X3.60	
: 1X6.23X7.79X3.60	
: 1X6.26X8.00X3.60	
: 1X6.26X7.96X3.60	
: 1X6.26X7.96X3.60	
: 8X6.07X7.96X3.60	
: 1X6.76X8.75X3.60	
: 1X10.89X1.97X3.60	
: 1X5.63X7.96X3.60	
: 1X4.98X9.34X3.60	
: 1X3.62X3.15X3.60	

: 1X5.50X8.75X3.60

: 1X6.22X7.74X3.60

: 1X2.06X1.50X3.60

Staff Room

Staff Room

Disabled Toilet

Toilet	: 1X1.64X2.66X3.60
Toilet	: 1X1.30X1.47X3.60
Varandhah	: 1X94.20X1.54X3.60
New	
Class Room	: 2X 7.50X 6.00 X3.60
Stair Room	: 1X 9.62X2.84X3.60
Sceince Lab	: 1X 7.50X12.20X3.60
Toilet Block	: 1X13.8723.45X3.60
Passage	: 1X25.26X1.88X3.60
Grill Portion	: 1X4.15X1.97X3.60
3. Second floor	
New	
Labs	: 2X 7.50X 6.00 X3.60
Stair Room	: 1X 9.62 X 2.84X3.60
Audio visual Room	: 1X 7.50X12.20X3.60
Toilet Block	: 1X13.87X3.45X3.60
Passage	: 1X25.26X1.88X3.60
Grill Portion	: 1X4.15X1.97X3.60
4. Terrace floor	
Stair Room	: 1X 9.62X2.84X3.60
5. Nature of defect if any	. 111 / 102/12/10 1/15/10
a) Foundation and basement	: NIL
b) Superstructure	: NIL
c) Doors and windows	: NIL
d) Wood work wrought and put up	: NIL
e) Roof	: NIL
f) Flooring	: NIL
g) Miscellaneous(Cracks if any)	: NIL
6. Any major defects noticed which will	
Render the building unsafe in any manner	: No
7. Whether maintenance work have been done properly	: Yes
8. Whether the structure is sound or not	: The Structure is Structurally sound
for conducting classes	under normal wind and weather
Condition	under normal wind and weather
Condition	

## Note:

- 1. The stability of the structure should be examined also with reference to location attitude intensity of wind exposure to flood etc.
- 2. Any additional observation deemed necessary for the certificate, may be furnished separately with the Certificate.

Certified that the school was inspected by me on 30.05.2023 and found fit to conduct classes for the period for the reason stated above.

Place: Pattanchery Date: 31/05/2023



Signature: Designation:

SUDHA. S
PEN: 667472
Assistant Engineer
LSGD Section
Pattanchery Grama Panchayath