




KERALA WATER AUTHORITY
OFFICE OF THE ASSISTANT EXECUTIVE ENGINEER
QUALITY CONTROL SUB DIVISION, THRISSUR - 680 005
Ph: 0487-2338380

Date :

BASIC WATER ANALYSIS REPORT
on Flood effected water sources

Name: Jose . E.V. Fr Paul Chittilappilly School
Administrator
Place: Engandiyu

Sl.No	Characteristics	Unit	Limit	Value
1	Colour	Coloured	Colourless	
2	Odour	Agreeable	Not agreeable	
3	Turbidity	NTU	1 to 5	0.3
4	pH		6.5 to 8.5	7.5
5	Electrical Conductivity	micro mhos/cm		315
6	Total dissolved Solids	mg/litre	500 to 2000	243
7	Residual Chlorine	mg/litre	0.2 to 1	NIL
8	Ammonia Nitrogen	mg/litre		NIL
9	Others	mg/litre		



[Signature]
Chemist/ Assi. Engineer

[Signature]
MANAGER
Fr. PAUL CHITTLAPPI LLY MEMORIAL
SCHOOL, CBSE/AH/931129

[Signature]
PRINCIPAL
Fr. PAUL CHITTLAPPI LLY MEMORIAL

30/06/2021

CERTIFICATE

This is to certify that, the education institution Mrs **FR. PAUL CHITILAPILLY MEMORIAL PUBLIC SCHOOL (CBSE Affiliation NO.931128)** located at Engandiyur Building no : 7/334 of Engandiyur Grama Panchayath,Thrissur district, Kerala State has been following good sanitary conditions and hygienic measures.

This certificate is issuing only for the purpose of renewal of the CBSE affiliation of said institution.

ENGANDIYUR CENTRE
29.06.21



HEALTH INSPECTOR
FHC ENGANDIYUR
HEALTH INSPECTOR
FAMILY HEALTH CENTRE, ENGANDIYUR
P.O. KUNDALIYUR, THRISSUR-680 616


MANAGER

FR. PAUL CHITILAPPILLY MEMORIAL
PUBLIC SCHOOL, CBSE/AH/931128
ENGANDIYUR, THRISSUR-680615
Ph: 2294483


PRINCIPAL

FR. PAUL CHITILAPPILLY MEMORIAL
PUBLIC SCHOOL, CBSE/AH/931128
ENGANDIYUR, THRISSUR-680615
Ph: 2294483

1 Name of the officer

MARY JOHN C

2 Period for which the certificate is issued

2020 - 2021

3 Nature of defect if any

- a. Foundation & Basement
- b. Superstructure
- c. Door & Windows
- d. Wood work wrought put up
- e. Roof
- f. Flooring
- g. Miscellaneous cracks etc



NIL

NIL

4 Any major defects noticed which will render the Building unsafe in any manner

YES

5 Whether the maintenance works have been done properly

6 Whether the structure is sound or not for conducting classes

YES. The structure of school building is found to be sound for conducting classes under normal weather conditions.

Note:- 1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood, etc.

2. Any additional observations is seemed necessary for the certificate may be furnished separately with the certificate.


Certified that the school was inspected by me on24.07.20 and found to be fit/unfit to conduct classes for the period2020-2021 for the reasons stated above.

Place:

Engandiyur

Date:

24.07.20



Signature

MARY JOHN C
ASST ENGINEER
LSGD SECTION
ENGANDIYUR GRAMA
PANCHAYAT

Designation:

PRINCIPAL