TO BE FILLED BY THE INSPECTING OFFICER

(Assistant Engineer/Assistant Executive Engineer)

Name of School

: Holy Cross Public School

1 Name of Officer

: Baburaj Koileriyan

2 Location

: Kudiyanmala, Eruvessi Grama Panchayath

3 Period for which the certificate is

: Up to 31st March 2020 : R.C.C. Framed

4 Types of building

G.F.		F.F.			S.F.
1)	6.50X6.05(Class Room)	1)	6.73X6.02 (Class Room)	1)	10.08x6.05(Yoga Room)
2)	6.35x6.05 - do -	2)	6.6x6.05 - do -	2)	10.08x2.42(Yoga Room)
3)	6.45x6.05 - do -	3)	6.35x6.05 - do -		
4)	6.63x6.12 - do -	4)	10.97x6.05 (Lab.)		
5)	6.65x6.02 - do -	5)	6.58x6.05 (Class Room)		
6)	6.72x6.05 - do -	6)	6.62x6.05 - do -		
7)	3.25x6.05 (H.M. Room)	7)	6.61x6.05 - do -	1	
8)	3.25x6.05 (Office)	8)	6.68x6.05 - do -		
9)	3.25x6.05 (Comp. Room)	9)	6.68x6.05 - do -	1	20 A

5 Nature of defect if any

a) Foundation and Basement

Nil

Superstructure

Nil

Doors and Windows c)

Nil

d) Wood work wrought and put up: Nil

Roof e) f) Flooring

Nil Nil

Nil

Miscellaneous(Cracks if any)

Any Major defects noticed which will render the building unsafe in any manner 7 Wheather maintenance work have been

No

done properly

Yes

- ⁸ wheather the structure is sound or not for Yes, The structure is safe for conducting classes under normal wind and weather conducting classes condition
- 1 The stability of the structure should be examined also with reference to location altitude intencity of wind exposure Note: to flood etc.

2

Any additional observation deemed necessary for the certificate may be furnished separately with the certificate

Certified that the School was inspected by me on .15-6-2019. And found to be fit /unfit to conduct classes for the period for the reasons stated above.

Place:

Irikkur

Signature

Designation

S.G.D. SUB DIVISION BLOCK PANCHAYAT, IRIKKUR