

Office of the,  
Executive Engineer,  
Public Works Division No.1, Chandrapur.  
Phone No. 250245  
E-mail Address::chandrapur1.ee@mahapwd.com


No. 4472 /D-2(1)/DM/2019.

Dated :: 16.07.2019

## BUILDING SAFETY CERTIFICATE

Certified that the Carmel Academy School, Chandrapur located at Survey No. 107/16A, 107/16B, Situated at Mouza Deai Govindpur Rayyatwari, DRC Road, Tukum Chandrapur. The Structural Engineer has inspected School building and given structural soundness certificate.

I also inspected the building, the building is structural sound and safe and fit for running school.

  
Executive Engineer,  
Public Works Division No.1,  
Chandrapur

Copy to Principal, Carmel Academy School, Chandrapur.