APPENDIX-XI

BUILDING SAFETY CERTIFICATE

No.: 9822

Date: 99/3/2

Certified that the existing building Carmel Academy School at Durgapur Open Cast Road, Chandrapu comprised of G+3 owned by Carmel Academy School, Tukum, Chandraur have complied with the Building Safety requirement in accordance with National Building code Rules, and verified by Shri A.W. Khan, Govt. Registered Structural & Chartered Engineer, Chandrapur & the Engineers of P.W.D. Sub Division No.1 also visited the said site on Dt. 07/03/2024 in presence of Fr. Jaison (Principal) and that the building is fit for occupancy upto classes XII with effect from 2023-2024 for a period of 3 (THREE) years accordance with rule and subject to compliance of the specific condition as appended.

- 1) Structural Stability should be examined also with reference to location, altitude, intensity of wind floor.
- 2) Fire safety inspection / report should be done by agency separately.

Issued on ______11-03-2024_ at Chandrapur by

* Strike out whichever is not applicable.

Sub Divisional Engineer Public Works Sub Division No. 1 Chandrapur Signature with Seal

Name: MR. SUNIL KUMBHE

Designat Public Wocksi Dn. INogineer
Chandrapur

Name & Address of Department / Office: Public Works

Division No Chandrapur.

Note: This certificate should be signed/ issued by Assistant Engineer & above officer of concerned Govt. Department only.

The filled up certificate should be either ion Hindi or English. If it is issued in vernacular language, transl notarized version in English is uploaded along with the original vernacular certificate as a single pdf.

Principal
B3M Carmel Academy
DOC Road, Tukum,
Chandrapur - 442 401



PRESIDENT
CMI SERVICE SOCIETY
TARSA, BAMINI
CALLARPUR-CHANDRAPUR DT.