Name of the officer

MARY JOHN C 2020 - 2021

Period for which the certificate is issued

Nature of defect if any

- a. Foundation & Basement
- b. Superstructure
- c. Door & Windows
- d. Wood work wrought put up
- e Roof
- f. Flooring
- Miscellaneous cracks etc

Any major defects noticed which will render the

Building unsafe in any manner

Whether the maintenance works have been done properly

whether the structure is sound or not for conducting YES. The Structure of classes School boulding is found to be Sound for conducting classes ander normal weather conduction.

NIL

NIL

YES

Note:- 1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood, etc.

2. Any additional observations is seemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on 24.07.20 and found to be fit/unfit to

Place: Engandigur

Date: 24.07.20

Signature

Designation:

Fr. PAUL CHITTILAPPILLY MEMORIAL PUBLIC SCHOOL, CBSE/Aff/93112 ENGANDIYUR THRISSUR-66061.

Ph: 2294483

MANAGER-