



### FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst.Engineer)

(Re:G.O.Ms.20/70/PWD Dt.23-01-1970)

1	Name of the Officer		Joseph Thomas
2	Name of the School		HOLY CROSS CONVENT SCHOOL,NEDUMKANDAM
3	Location with name of Education District/Sub.District		Idukki -Nedumkandam
4	Classification of Building as specified in column 4 of the application for fitness certificate and size	GF	25.00*28.00*3.60M
		GF	24.40*10*3.60M
		FF	25.00*28.00*3.60M
		FF	24.40*10*3.60M
		SF	25.00*28.00*3.60M
		SF	24.40*1000*3.60M
		GF	56.10*6.65*3.50M
		GF	7.35*14.25*3.50M
		FF	7.20*14.25*3.50M
		FF	56.10*9.65*3.50M
		FF	7.35*14.25*3.50M
		SF	7.20*14.25*3.50M
		SF	56.10*9.65*3.50M
		SF	7.35*14.25*3.50M
			GF
		GF	6.10*10.40*3.50M
		GF	31.10*10.20*3.50M
		GF	9.30*6.10*3.20M
		FF	3.15*10.20*3.50M
		FF	6.10*10.40*3.50M
		FF	31.10*10.20*3.50M
		FF	9.30*6.10*3.20M
		SF	3.15*10.20*3.50M
		SF	6.10*10.40*3.50M
		SF	31.10*10.20*3.50M
		SF	9.30*6.10*3.20M
5	Period for which the certificate is issued	2025 - 2026	
6	Nature of defects,if any		
	a) Foundation and basement	Nill	
	b) Superstructure		
	c) Doors and Windows		
	d) Wood work wrought and put up		
	e) Roof		
	f) Fllooring		
	g) Miscellaneous (Cracks ,etc)		
7	Any major defects noticed which will render the	Nill	

8	Whether maintenance works have been done properly					
9	Whether the structure is sound or not for conducting classes	Structure is sound under normal weather /climate condition				
<p><i>Note: 1. The stability of the structure should be examined also with reference to location ,altitude,intenity of wind,exposure of flood etc.2.Any additional observations if deemed necessary for the certificate may be furnished separetely with this certificate.</i></p> <p style="text-align: center;"><b><u>CERTIFICATE</u></b></p> <p>Certified that the school building was inspected by me on 10/09/2025 and found to be FIT ,to conduct classes ,for the period 2025-2026 for the reasons stated above.</p>						
<table border="1" style="width: 100%;"> <tr> <td style="width: 15%;">Place:</td> <td>Nedumkandam</td> </tr> <tr> <td>Date:</td> <td>10/9/2025</td> </tr> </table> <div style="text-align: right; margin-top: 20px;">   <b>Assistant Engineer</b>  <b>JOSEPH THOMAS</b>  PEN:192618  ASSISTANT EXECUTIVE ENGINEER  NON-CADRE  LSGD- LID&amp; EW SECTION  NEDUMKANDOM </div>			Place:	Nedumkandam	Date:	10/9/2025
Place:	Nedumkandam					
Date:	10/9/2025					





### FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst.Engineer)

(Re:G.O.Ms.20/70/PWD Dt.23-01-1970)

1	Name of the Officer		Joseph Thomas
2	Name of the School		HOLY CROSS CONVENT SCHOOL,NEDUMKANDAM
3	Location with name of Education District/Sub.District		Idukki -Nedumkandam
4	Classification of Building as specified in column 4 of the application for fitness certificate and size	GF	25.00*28.00*3.60M
		GF	24.40*10*3.60M
		FF	25.00*28.00*3.60M
		FF	24.40*10*3.60M
		SF	25.00*28.00*3.60M
		SF	24.40*1000*3.60M
		GF	56.10*6.65*3.50M
		GF	7.35*14.25*3.50M
		FF	7.20*14.25*3.50M
		FF	56.10*9.65*3.50M
		FF	7.35*14.25*3.50M
		SF	7.20*14.25*3.50M
		SF	56.10*9.65*3.50M
		SF	7.35*14.25*3.50M
		GF	3.15*10.20*3.50M
		GF	6.10*10.40*3.50M
		GF	31.10*10.20*3.50M
		GF	9.30*6.10*3.20M
		FF	3.15*10.20*3.50M
		FF	6.10*10.40*3.50M
		FF	31.10*10.20*3.50M
		FF	9.30*6.10*3.20M
		SF	3.15*10.20*3.50M
		SF	6.10*10.40*3.50M
		SF	31.10*10.20*3.50M
		SF	9.30*6.10*3.20M
5	Period for which the certificate is issued	2025 - 2026	
6	Nature of defects,if any		
	a) Foundation and basement	Nill	
	b) Superstructure		
	c) Doors and Windows		
	d) Wood work wrought and put up		
	e) Roof		
	f) Fllooring		
	g) Miscellaneous (Cracks ,etc)		
7	Any major defects noticed which will render the	Nill	