

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

Asst. Engineer
Mangalathu Public School
Thalakkal, Alwaye.

G.F - 786.30 m²
F.F - 782.50 m²
S.F - 89.81 m²
S.F - 692.69 m²
T.F - 38.35 m²
2021 - 22

5. Period for which the certificate is issued
6. Nature of defects, if any

- a) Foundation and basement
- b) Superstructure
- c) Doors and Windows
- d) Wood work wrought and put up
- e) Roof
- f) Flooring
- g) Miscellaneous (Cracks, etc.)

Nil
R.C.C. Spread Footing
Column Framed Structure
Wooden and built up Steel Section

R.C.C. Roof
Tiled Flooring

7. Any major defects noticed which will render the building unsafe in any manner

Nil

8. Whether maintenance works have been done properly
9. Whether the structure is sound or not for conducting classes

Yes
Yes. Structure is sound under normal weather condition.

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 24-09-2021 and found to be fit / unfit to conduct classes, for the period 2021 - 22 for the reasons stated above.

Place : Kakkannad
Date : 24-09-2021




Assistant Engineer
ASSISTANT ENGINEER
P.W.D. BUILDING SECTION
EDAPPALLY
CIVIL STATION KAKKANAD