

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)


(Re GO Ms 29/70/PWD Dt. 23-01-1970)

1. Name of the Officer Praveen P L
2. Name of the School Mannan Memorial English Medium School
3. Location with name of Education District Sub District
4. Classification of Building as specified in Form 1 of the application for Fitness Certificate and size Rcc Roofed Poshole Slabbed building
(35.34m x 8.81m)
5. Period for which the certificate is issued 2021 - 2023
6. Nature of defects, if any
 - a) Foundation and masonry
 - b) Superstructure
 - c) Doors and Windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous cracks etc.} NIL
7. Any major defects noted which will render the building unsafe in any manner
8. Whether repairs or works have been done properly YES
9. Whether the structure is suitable for conducting classes Sound & sturdy, normal climatic conditions


Note: 1. The stability of the structure should be examined also with reference to location, absolute intensity of wind, exposure of front etc. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 13/06/2022 and
 found to be fit unfit to conduct classes for the period 2021 - 2023 for the
 reasons stated above for the

Place Pullyoor
 Date 13/06/22
 Self Attested

 PRINCIPAL




 Assistant Engineer
 LSGD Section
 Assistant Engineer
 Pullyoor, Changanu