

**TO BE FILLED BY THE INSPECTING OFFICER
(ASSISTANT ENGINEER)**

SREENARAYANA VIDYAMANDIR
CENTRAL SCHOOL KODALY

building No.1

1 Name of Officer :

V.S SARASWATHY Assistant Engineer LSGD
Section Mattathur GP

2 Period For Which Certificate is Issued:
after flood

2019-2020 Academic Year

3 Nature of Defect if Any

- (a) Foundation And Basement
- (b) Superstructure
- (c) Doors & Windows
- (d) Wood WORK Wrought Put UP
- (e) Roof
- (f) Flooring
- (g) Miscellaneous Cracks Etc

The Structure is Seen Column Framed
Structure. Defects nil

Nil

4 Buliding Unsafe If Any Manner

NIL

5 Whether The Maintenance work Have Been done
Properly

yes

6 Whether The structure is Sound or not Conducting
Classes

The Structure is Seen Sound Enough Under
Normal Weather Condition to Conduct
Classes During 2020-2021

Notes :- 1. The Stability of The structure should Be Examined Also With Refernce to location
altitude intensity of wind exposure to flood , etc

2 Any Additional Observation is Seemed Necessary For the Certificate May Furnished
Separately with certificate
as per attached drawing and application

Certified That the school Was Inspected Me on 28.05.2020 Found to be Fit / to Conduct
Classes For the Period 2020-2021 stated Above

G F CLASS ROOMS 18nos - 6.17*6.78m
 4 nos - 6.17*10.30m
 2 nos - 3*6.50m

F F CLASS ROOMS 12nos - 6.17*6.78m
 1nos - 3*6.50m
 1nos - 6.17*10.30m

Library 6.30*3.10m
 6*9.40m
 7.20*6.10m

Place : Mattathur
Date: 28.05.2020

Signature
Designation
Assistant Engineer, LSGD Section Punnapoor
Kulam GP

Saraswathy V.S
11/06/2020

SARASWATHY V.S
ASSISTANT ENGINEER
L.S.G.D. SECTION
MATTATHUR
GRAMA PANCHAYATH

[Handwritten Signature]



**PRINCIPAL
USHA P.S.**

Sree Narayana Vidya Mandir
Central School, Kodaly
CBSE Affi.No. 930975

**C.G. RAJAN
SECRETARY
S.N. TRUST, KODALY
REG. NO. 4415**

