

FITNESS CERTIFICATE

TO BE FILLED BY THE INSPECTING OFFICER

(ASSISTANT ENGINEER)

- 1 Name of the Officer : ELDO SIMON
- 2 Name of the School : ST. LIOBA Academy
- 3 Location with Name of Educational District
- Sub District : Chalakudy Sub Dist. Irinjalakuda Dist.
- 4 Classification buildings as specified in Col. 4 : 7.20 *6.60* 3.70 (7-class rooms) GF
- of the application for fitness certificate & Size : 7.20* 6.60* 3.70 (7-class rooms) FF
- : 7.20* 6.60* 3.70 (4-class rooms) SF
- 5 Period for which the certificate is issued : 2025-26
- 6 Nature of Defect if any
- h) Foundation and Basement : Good Condition
- i) Super Structure : Good Condition
- j) Doors and Windows : Good Condition
- k) Wood Work Wrought put up : Nil. Damaged wood replaced.
- l) Roof : Good Condition
- m) Flooring : Good Condition
- n) Miscellaneous cracks etc : Cracks affecting safety not visible
- 7 Any major defects noticed which will render the building unsafe if any manner : No
- 8 Whether the maintenance works have been done properly : Yes
- 9 Whether structure is safe for conducting classes : Sound fit under normal wind and weather conditions.

CERTIFICATE

Certified that the school building was inspected by me on 26-05-2025 and found to be fit/~~unfit~~ to conduct classes, for the period **2025-26** for the reasons stated.

Place: Kodakara
Date: 28-05-2025

(Seal)




Assistant Engineer
ELDO SIMON
PEN: 859565
ASSISTANT ENGINEER
LSGD - LID&EW SECTION
KODAKARA