

FITNESS CERTIFICATE

to be filled by the inspecting officer(Assistant engineer)

- 1 Name of the officer **NAVYA V JOSEPH ,Assistant Engineer**
- 2 Name of the School **St. Thomas Public school, Enanthi**
- 3 Location **Enanthi, Nilambur**
- 4 Period for which the certificate is issued **2025-26**
- 5 Types of buildings
- | | L(m) | B(m) | H(m) | Class rooms |
|--------------------------|-------|------|------|---------------|
| RCC Roof Building | | | | |
| GF | 6.00 | 6.00 | 3.70 | 4 nos |
| " | 9.50 | 6.20 | 3.70 | 1 no |
| " | 14.10 | 8.15 | 3.70 | Library |
| " | 9.56 | 8.13 | 3.70 | Office |
| FF | 9.20 | 6.20 | 3.70 | 1 no |
| " | 9.00 | 6.20 | 3.70 | 1 no |
| " | 6.00 | 6.20 | 3.70 | Staff room |
| " | 9.50 | 6.20 | 3.70 | 1 no |
| " | 7.00 | 8.15 | 3.70 | 2 nos |
| " | 3.33 | 8.23 | 3.70 | Computer room |
- 6 Nature of defects if any **NIL**
- a Foundation and basement **NIL**
- b Superstructure **NIL**
- c Doors and windows **NIL**
- d Wood work wrought and putup **NIL**
- e Roof **NIL**
- f Flooring **NIL**
- g Miscellaneous(cracks if any) **NIL**
- 7 Any major defects noticed which will render the building un safe in any manner **NIL**
- 8 Whether the maintenance works have been done properly **YES**
- 9 Whether the structure is sound or not for conducting classes. **Sound for conducting classes under normal weather and wind conditions as on 22-05-2025**

Note 1: The stability of the structure should be examined also with reference to location altitude,intensity of wind,exposure to flood etc

Note 2:Any additional observation deemed necessary for the certificate,may be furnished seperately with the certificate.

Certified that the Schools was inspected by me on 22-05-2025 and found to be fit to conduct classes for the period under normal weather conditions.

Place:Nilambur

Date:27-05-2025



29/05/25
Assistant Engineer
Nilambur Municipality