## BUILDING SAFETY CERTIFICATE

No.

Dated: 22.8.2025

It is certified that the existing building ST.THOMAS PUBLIC SCHOOL at Enanthi is having block(s)/Floor(s) as per details below:

Detail of Block(s) in	Block	Block	Block	Block	Block	Block
school	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor(s) in the	3,GF,FF&SF					
Block	1890.48 m2					

The building is owned/occupied by ST.THOMAS PUBLIC SCHOOL have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of ALD QEW SECTION, NILDINGUE, MUNICIPOLIT, (Name of Department/Govt.) on 18 2025 (date of inspection) in the presence of Manager Sr. Rose Mary and that the building/premises is fit for occupancy for running school with effect from 2025 for a period of 2026 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. GF -15.5 x 6 x 3.7 m

14.10 x 8.15 x 3.7m

9.56 x 8.13 x 3.70m

2.  $FF - 33.7 \times 6.20 \times 3.7 m$ 

7 x 8.15 x 3.7m

3.33 x 8.23 x 3.70m

3. SF - 34.12 x 6.16 x 3.70m

14 x 8.15 x 3.70m

8.30 x 7.38 x 3.70m

3.40 x 8.15 x 3.70m

Issued on 22.8.2025 at Enanthi by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal:

Name:

Designation: \_

n: ASSISTIMAT ENGINEER

Name & Address of Department/ Office: NILTOWBUR

NILDIABOR MONICIPALITY

68 | Page

Sa Rose Clax 26
Manager
mas Public School

St. Thomas Public School Enanthy. Nallamthanni PO. Malappuram Dt. 679 330



ST. THOMAS PUBLIC SCHOOL EN ANTHI NILAMBUR - PIN: 679 331